

**June 15 Night Shift  
June 16 Day Shift  
DAY 52**

*the*  
**Ursa Major Facts**

**SAFETY FOCUS: CLEANING UP**

We have units in various stages of Turnaround, start-up, de-mob and executing work. Maintaining a clean and tidy work environment is of the utmost importance for preventing incidents and injuries.

Watch for hidden hazards:

- Objects such as tools, materials etc. hidden in folded fire blanket or left on leading edges
- Pinch Points
- Line of Fire
- Debris in half/full masks that have not been properly stored

Ensure all loads being transported via forklifts are properly secured.

Do not stack or pile materials unevenly, high, or leave them unsecured. They could topple over and become tripping hazards or dropped objects.

Clean up your work area as you go.

Be aware of your surroundings and intervene when housekeeping hazards are observed.

Teamwork is the key to a clean work area. Good housekeeping reduces incidents, improves morale and increases efficiency.

**SAFETY HEALTH & ENVIRONMENT**

June 15 @ 6:00	Previous 24 Hours	Total to Date	First Aid	Record. Injury
<b>URSA MAJOR</b>				
# of Med Center Visits	0	68		
# of Injuries	0	42	34	8
# of Incidents	2	86		
# Shifts Injury Free		2		

**Ursa Major Incident Communication**

With the temperatures increasing, the potential for workers to experience heat stress also increases.

Please take all precautions to avoid heat stress with water intake and rest breaks. Drink at least one cup of water every 20 minutes.

Symptoms of heat stress to watch for in yourself & others: Muscle cramps, headache, nausea, weakness, dizziness, faintness, extreme tiredness, fast breathing, vomiting, very red face and skin, excessive sweating, stumbling or confusion.

**Fort McMurray**

Sun. Evening Sunny  <b>22°C</b> Feels like 22	Sun. Overnight Clear  <b>10°C</b> Feels like 9	Mon. Morning Variable cloudiness  <b>14°C</b> Feels like 14	Mon. Afternoon Variable cloudiness  <b>21°C</b> Feels like 21
---	--	---	---

**LEADER'S QUESTION TO WORKERS:  
What are you going to do to keep your work area safe??**

INCIDENT DATE	DIVISION	COMPANY	SEVERITY	BODY PART	INCIDENT DESCRIPTION
June 9	Hydro	Ed. Ex.	FA	Hands	Worker hand contacted the scaffold steps; scraping his knuckles.
June 9	Hydro	Ed. Ex.	MC Visit	Leg	A worker was working as Spark Watch in plant 9-2, under the furnace. Strain in his leg.
June 9	Hydro	Clayburn	FA	Hands	Stainless steel pin impaled EE's right wrist.
June 11	Conversion	Horton	FA	Back	Crawling out manway hyperextended lower back - felt pain
June 12	Hydro	Ed. Ex.	FA	Head	Hot metal slag flew landing on worker's neck.
June 13	Conversion	Horton	MC Visit	Trunk	Worker felt pain between the spine and shoulder blade after opening heavy wash car door.
June 14	Hydro	Aluma	MC Visit	Internal	Worker was modifying a scaffold when he noticed a strong odor and inhaled smoke.

DATE	BACK	EYES	FEET	FINGERS	HANDS	HEAD	INTERNAL	LEGS	SHOULDER	TRUNK
June 8 to June 14	1	0	0	0	2	1	1	1	0	1
TOTAL TO DATE	9	9	4	10	4	7	11	8	2	4

**Discarded parts and tools don't put themselves away.**



**Practice Good Housekeeping!**